Herpain



SAUDI ARABIA EMBASSY

Renovation of the Embassy of Saudi-Arabia

Renovation of the Embassy of Saudi-Arabia

Avenue Franklin D. Roosevelt,
45 à 1050 Bruxelles

Herpain





SAUDI ARABIA EMBASSY

Property Owner
Kingdom of Saudi-Arabia
Architect
Marcellino SAAB
Structural engineer
Soliprom
Safety coordinator
Mommaerts-Safety

Category	**Others**
Works beginning date	07/05/2012
Delivery	30/09/2016
Works costs	10.228.633,00 EUR
Floors	R + 3
Overground surface	2.261 m²
Basement surface	755 m²









